

# N510 IP PRO Release notes 42.078

## Release date:

06-2013

## Version:

42.078

## What's new:

Access code special treatment in call-list for Nordic customer

The feature is by default disabled (not available in the WEBUI) It can be enabled via provisioning. Values which has to be adapted:

Config Byte:

BS\_CUSTOM.ucAkzVoipNotUsedNumberLength.

Values:

- 0x00 – feature available in WebUI but not working
- 0x01-0x09 – feature available in WebUI and working for numbers n-digits long and shorter
- 0xFF – feature disabled (not available in webUI) – the default one

Other values are not allowed

## Enhancements:

- ...

## BugFixes:

- Instability of Base-station in some environments.

## Known Issues:

- ....

## Download URL:

## How to update:

Via the webpage:

1. Settings » Management » Firmware update
2. Enter the URL for the new firmware in the **User defined firmware file:** field
3. Click on the button: **Update firmware**

The screenshot shows a web interface for updating firmware. On the left is a navigation menu with categories: Network, Telephony, Messaging, Info Services, Directories, Management, and Firmware Update (highlighted). The main content area is titled 'Firmware Update' and contains the following fields and options:

- Data server:** A text input field containing 'profile.gigaset.net/device'.
- User defined firmware file:** An empty text input field.
- Automatic check for software updates:** Radio buttons for 'Yes' (selected) and 'No'.
- A paragraph of text: 'On starting the firmware update, the device checks if the requirements of a successful firmware download are fulfilled. The firmware is then downloaded without additional feedback. During the download and update, the handset / base connection is lost. A successful update results in the handset re-establishing the base connection.'
- Update firmware** button.

