

DE310/410 IP PRO 02.00.11

Release Date:

November 2014

Version:

02.00.11



Important

Because of improvements in the software like adaptive jitter buffer and other new features we strongly advise to **factory reset** the device after the upgrade.

What is new?

- [Function keys can be blocked for auto provisioning](#)
- [Broadsoft XSI interface](#)
 - Call Divert
 - Do Not Disturb
- Incoming name and number are displayed static and not rotating
- [Possible to display CLIP info coming from "FROM Header" or "P-asserted identity header"](#)
- Add danish and swedish language to device
- Integration of Adaptive Jitter Buffer and DSP Leveling (<http://<IP-addr.>/jbuf.html>)
 - Improved audio quality
 - Jitter Buffer adapts to network quality (Better network mean less delay)
- Automatic Reboot option via Web-UI (login the Web-UI as admin, then change to <http://<IP-addr.>/reboot.html>)

Enhancements.

- Improved DNS handling in case of bad DNS service.
- Do not show name, date and time on the display when receiving SIP messages, only show the content.
- Usage of hyphen in BLF should be possible
- TELES: Handling of XCID parameter
- [HTTP digest username and password via phone keypad.](#)

Bugfixes

- Name of SIP account is flickering
- SRTP and TLS - no outgoing RTP packets
- Robot voice with latest software versions
- SRTP parameter is not set after provisioning (you have to save web ui page manually)
- Turkish language for MMI and Web GUI
- Name out of phonebook entry is not shown after SW-update to V02.00.10
- Incoming call behind Gigaset T300/T500 not possible incoming invite is answered with "BAD request".
- Dutch Translation.
- CALL-ID should be changed because of SIP ALG routers.
- XML code on BLF key via provisioning 64 characters.
- Robot voice.
- In case of Static IP address, speech path is distorted.
- Provider TELES: Reboot occurs if own number dialled
- Stability improvements.
- [Provisioning] B_UNATTENDED_XFER does not work.
- DExxx rejects INVITE
- B_AUTOMATIC_DTMF_(N) does not work when downloading profile from country list.
- Wrong default setting MWI
- INVITE problem with a terminating application.
- No reaction to the 407 Proxy Authentication Required on sending REFER
- Quoted Display Name must allow comma sign.
- Transferor reboots after performing "consultation transfer before answer".
- Not possible to make call from telephone book after upgrade.
- LDAP - empty entry (no phone numbers) - device will reboot.
- One way audio with ZTE IMS Core platform.
- [Alarm] If we pick up the handset when alarm clock is ringing and then press "OFF" nothing will happen (alarm will be ringing).

- If PAI available Diversion User Part is not displayed.
- LDAP: wrong timezone is displayed when viewing LDAP entry
- Provisioning: Certain Parameter not adopted in combination with Extended_Profile.

Known Issues

-



[Download](#)