

N510 IP PRO Release notes 42.081

Release date:

08-2013

Version:

42.081

What's new:

- Access code special treatment in call-list for Nordic customer.

Enhancements:

- DTMF control already at 180 ringing state and not only after 200 ok.
- Gigaset R630 support.
- Auto-provisioning update timer no reboot needed to activate.
- TR-069 - Zero Touch Activation
- Assign NTP server via DHCP
- Possibility to accept non trusted certificates automatically

BugFixes:

- Instability of Base-station in some environments.
- Language problem (Czech language)
- Radio-buttons for Date & Time are on wrong position
- SIP call cannot be answered when is made 2s after the last one
- New Parameters do not take effect after provisioning using plain XML content
- Changing the timer interval from 24h-random to a fix time stops the regular check
- Text on Info Services settings page is missing

Known Issues:

-

Download URL:

How to update:

Via the webpage:

1. Settings » Management » Firmware update
2. Enter the URL for the new firmware in the **User defined firmware file:** field
3. Click on the button: **Update firmware**

The screenshot shows a web interface for 'Firmware Update'. On the left is a navigation menu with categories: Network, Telephony, Messaging, Info Services, Directories, Management, and Firmware Update (highlighted). The main content area has the title 'Firmware Update' and the following fields and options:

- Data server:** profile.gigaset.net/device
- User defined firmware file:** (empty text input field)
- Automatic check for software updates:** Yes No

Below these fields is a paragraph of text: "On starting the firmware update, the device checks if the requirements of a successful firmware download are fulfilled. The firmware is then downloaded without additional feedback. During the download and update, the handset / base connection is lost. A successful update results in the handset re-establishing the base connection." At the bottom of the form is a button labeled "Update firmware".

