

T300/T500 - BLF keys

Issue: BLF keys on Gigaset DE devices behind the Gigaset T300/T500 are not signalling the status of devices or modules.

Cause: hint.conf on the PBX is wrong

Solution:

- Program key on a device using the web-interface of the PBX.
- Save settings.
- hint.conf is generated new