

Maxwell 10 Build 1.2.9 (Beta Release)

Release Notes

Release Date:


07/07/2015

Version:

1.2.9

New Features and improvements

- Optimized search engine in directory
- DND button on Home Screen



Bugfixes

- DECT handset stops working after sometime
- Speech path is routing to DECT Handset when call accepted via Handsfree
- Call terminates while pressing DECT/EHS Headset PTT button During Open listening mode
- Audio not routing to corded handset after open listening mode with DECT headset
- Voicemail notifications are not navigating to Call list app for UCI based (Starface) phone systems
- Audio route problems when off-hooking corded HS during dial

- [USB Headset] Incoming call ringing sound is discontinuous/switched between Handsfree and USB headset
- DECT HS cancels the outgoing call after taking it up from the cradle
- DECT settings menu cannot be opened
- Skype call not establishing when External camera is connected in Maxwell
- Audio device Priority is not working properly with Handset and Headset
- Call list cannot be opened
- Phone app UI showing wrong device during routing
- Some italian strings have to be corrected
- Device hangs during boot up
- Outgoing calls are not possible behind German-Telekom-IP-All accounts
- Create Open-Source-package and enhance Android licence informations
- Unify OSV - Maxwell stops Phone App after hold
- There is a leading (wrong) "null" to all names if "LDAP-Search at incoming calls" is enabled
- "Requested number does not match Try again" - using call list
- The letter ß cannot be displayed in android menu
- Speech dropouts in RTP sending direction when pressing volume buttons on handset
- Missing Announcement at call setup
- In case DECT is active, in some situations a high frequency noise can appear (through loudspeaker). To stop this sound, a reboot is necessary.

Known Issues (will be fixed in next official release)

Corded handset not working sometimes. A reboot solves the issue.

Doubled acoustics when picking up a call with DECT handset (audio on handset AND Maxwell 10).


Distorted audio on handsfree with narrowband calls (G.711 and progressinband=yes).

Call is hung up sometimes during call-setup with DECT handset.

Firmware update

Online

In the webinterface of the Maxwell 10 go to:



Settings - System - Firmware update

server URL = <http://profile.gigaset.net/device/latest>

Click on Update firmware and the latest Firmware that is online will be downloaded.

Manual

First download the Firmware on your PC and unpack the zip file. You will get a .txt file with the Open Source License text and an encrypted zip file which is your firmware image.

In the webinterface of the Maxwell 10 go to:

Settings - System - Firmware update

? Unknown Attachment

Click on "**Choose File**" and select the Firmware file.

Click on "**Load**" to start the upgrade.

Download

Software versions	
DVF9919	03.6414
Build number	80_1_1.2.9