

Maxwell 10 Build 1.2.16

Release Notes

Release Date:


09/09/2015


Version:

1.2.16

New Features

- general stability improvement
- [VLAN support](#)
- 3rd party App support for Audio
- **? Unknown Attachment**
- [Automatic reboot option](#)
- QoS Settings for video rtp
- Adding Danish/Swedish/Polish language
- Updated Italian language
- MWI messages for missed calls and voicemail are shown in the notification bar
- Optimized search engine in directory
- DND button on Home Screen
- Firmware upgrade tone loudness
- Broadsoft improvements
- Optimized search engine in directory
- DND button on Home Screen





- New localization files for Italy
- MWI messages for missed calls and voicemail are shown in the notification bar

? Unknown Attachment

- Automatic reboot option

? Unknown Attachment

- Interop improvements for Polycom video calls
- QoS Settings for video RTP

? Unknown Attachment

Bugfixes

- Malfunctioned dial tone with narrow band codecs
- DND icon not working sometimes with UCI configuration
- Maxwell Unauthenticated Auto provisioning
- Maxwell Unauthenticated Admin Password Reset
- Robot voice when accepting call waiting
- Robotic Noise when conference call is done Hold and resume, and the participants has different codecs (NB and WB)
- Changing corded HS or DECT HS volume via volume bar has no effect
- Incorrect offer-answer model
- Call drops
- Broadsoft - XSI Call Forward and DND retrieval interval is very short
- Maxwell SW 1.1.0.1 Session timer issue, calls disconnected after 30 minutes
- [Call List] Broadworks - Call History HTTP request suboptimal
- Call Divert App: XSI modifying doesn't work after 302 Redirect
- DECT on/off switch: If this Android setting is switched to off the DECT transmission has to be switched off
- SW 1.0.7 Auto provisioning - Server URL in web-interface
- Door interphone „key“ button Maxwell 10
- Unify - Display Problem transfer call
- High beep tone for 4 seconds when clicking on a button instead of normal touch tone
- No registration from handset possible after factory reset
- Loud noise after starting firmware update
- EHS / DHSG: Protocol issue
- Not possible to answer the call with DECT HS
- Set Default date as 1st Jan 2014
- Maxwell Unauthenticated Admin Password Reset
- Maxwell Unauthenticated Auto provisioning
- Interop improvements for Polycom video calls
- Maxwell speakers are not switched off when Maxwell is in idle state
- DTMF tones are not transmitted correctly
- Character '+' is encoded as '%2b' in SIP message
- SIP accounts and web-GUI displays incorrectly names with umlauts
- Problems with TLS registration
- EHS/DHSG headset improvements
- DECT battery charging icon is missing in the status bar
- Provisioning improvements
- Door intercom „key“ button Maxwell 10 does not send DTMF code
- DECT handset improvements

- German-Telekom-IP-All accounts improvements.
- General Bugfixes


Known Issues

-

Firmware update

Online

In the webinterface of the Maxwell 10 go to:



Firmware Update

Data server

..set custom url here

Settings - System - Firmware update


Data server URL = http://profile.gigaset.net/device

Click on Update firmware and the latest Firmware that is online will be downloaded.

Manual

First download the Firmware on your PC and unpack the zip file. You will get a .txt file with the Open Source License text and an encrypted zip file which is your firmware image.

In the webinterface of the Maxwell 10 go to:



User-defined firmware file No file chosen

Settings - System - Firmware update

Click on "Choose File" and select the Firmware file.

Click on "Load" to start the upgrade.



Software versions	
DVF9919	03.64A16
Build number	80_1_1.2.16