Maxwell 10 Build 1.2.20.1

Release Notes

Release Date:

Febr 2016

Version:

1.2.20.1

Improvements

- Door Intercom improvements
 - O Door intercom and Camera with login authentication
 - o jpg reload rate improvement
 - Enlarged video size for incoming calls via video door intercom
- Firmware upgrade via USB Pen Drive
- Google Play: Apps with portrait mode can now be installed on Maxwell
- Notification for helper app
- Broadsoft Improvements
- · Turkish language implementation

Bugfixes

- · Mode of the WEB-UI switch in the Android settings can't be changed via WEB-UI
- Call is initiated automatically after around 5sec when handset is pickup from the cradle and number is typed
- Bad sound quality in 3rd party audio apps
- · Outgoing call started in handsfree when corded/DECT HS is laying off-hook
- Not possible to answer call with DECT HS
- Audio route changing during busy tone
- Shrill noise observed on Maxwell 10 device
- Audio is not routed to EHS headset when switching between Corded handset and EHS headset
- No Audio when Dect Headset and USB headset is connected
- · Maxwell's sip account deregistering after receiving multiple incoming calls
- Error code instead of a busy tone
- Dialing with * is not possible
- System updates shows wrong information
- no access with google chrome to any URL
- Phone is not sending any DNS queries to DNS server if IPv6 is used
- No speech path during call when HDMI is connected
- DECT continually starts dialing when laying on cradle
- Automatic & Manual firmware upgrade happening simultaneously
- Info widget not displaing call diverts
- Directory Application Crash when sorting done without any contact
- Widget for "Programmable Keys" causes laggy behaviour and freezes of "Overview"
- Call automatically terminated after call waiting ended
- Maxwell not sending user agent after call crash
- No speechpath during attended transfer
- Calls accepted with DECT headset are moved to corded HS
- DECT Headset not De registering sometimes
- Robot voice during conference
- Maxwell Unauthenticated Admin Password Reset
- Error code instead of a busy tone
- Audio path is changing to hands free speakting if called party is busy and the audio device headset or handset was used
- Wrong message in programmable key widget
- · Call termination


Known Issues

•

Firmware update

Online

In the webinterface of the Maxwell 10 go to:



Settings - System - Firmware update

Data server URL = http://profile.gigaset.net/device

Click on Update firmware and the latest Firmware that is online will be downloaded.

Manual

First download the Firmware on your PC and unpack the zip file. You will get a .txt file with the Open Source License text and an encrypted zip file which is your firmware image.

In the webinterface of the Maxwell 10 go to:



Settings - System - Firmware update

Click on "Choose File" and select the Firmware file.

Click on "Load" to start the upgrade.



Software versions	
DVF9919	03.64A16
Build number	80_1_1.2.20.1