Firmware S650H

Software 76.02

Wrong number is using during automatic redial

SUOTA improvements

Quicksync call per Bluetooth headset

Software version 75.06

- [Copy to Base Directory] New entry is tripled (or more)
- Speechpath is not loud enough
- Line info does not occur in Call lists

Software version 74

Various bugfixes, amongst others, in following sections:

- Line info does not occur in Call lists
- Swiss Provider changes
- Copy to Base Directory - New Entry is trippled
- Speech-path not loud enough
- Routes audio to handset and not headset when BT is connected
- Base connection - "no base" delay
- No voice output when trying to listen to messages on AM
- CAT-iq improvements
- No possible to set 'Call lists' on Left Soft Key
- PIN protected key lock
- [Redial List]Entry is cloned after made outgoing call
- Muted incoming call
- Right soft key (Save) does not react during changing volume
- SUOTA improvement
- Many other minor improvements

Software version 63

Various bugfixes, amongst others, in following sections:

- CLIP Picture and VIP melody
- SUOTA
- CAT-iq
- Interoperability with Deutsche Telekom Speedport Hybrid and Type C
- Bluetooth pairing

Software version 60

Change default ringer melody

Enable silent charging icon

Gigaset Animation is not played when key-lock active and HS put in charger

Appointment signal is changed for all appointments, not individually.

SUOTA improvements

Software version 59

Local Call list for GAP mode

Implementation for CAT-iq 2.0 protocol

First implementation of SW update over the Air (SUOTA) (Has to be supported by DECT base)

List of anniversaries problem when number of anniversaries is greater than 255

The corded headset alert volume during incoming call with all ring tones off