N510 IP PRO Release notes 42.242

Release status:

- Released

New features:

- Broadsoft XSI Phonebooks

Bug-fixes and improvements:

Localization

- Turkish language/character set also in menus/directory contents
- Turkish translations updated
- Hungary: Call progress tone scheme added

SIP Update/call transfer

- SIP UPDATE can be enabled/disabled in Web Configurator
- Unexpected call termination after n minutes because of SIP UPDATE - '501 Not Implemented Here' - fixed
- CLIP/COLP not updated via re-invite message - fixed
- Lack of speech-path when trying to transfer call - fixed

Security

- Remove expired/not needed certificates
- Offer current cipher suites for successful TLS handshake
- HTTPS phone-book: certificate not loaded automatically - fixed by added TLS Support switch and web configurator setting
- Device no longer goes to a loop when checking details of the first certificate

Various

- SUOTA: Handset sends invalid SW version within SW version indication message fixed
- Web Configurator status page enhanced
  - Uptime since last power interruption
  - Details of registered handsets: product type, part-number, firmware version, connection status with check status button
- MTU negotiation (PMTUD) improved
- Blocking Register when router misses WAN link
- Send key does not work properly in "Next Call Anonymous"
- Blocked number is no longer visible in redial list
- LDAP "Service not available" - fixed

Known issues:

- ...