

DX800 Release notes 158

Release date:

02-2014

Version:

158

What's new:

- Support of handsets with touch based user interface (SL910H, S820H, SL930H)
- Support of Repeater 2.0
- Country specific call progress tones
- Supply dial tone on FXS port, depending on setting (FAX or phone use) and selected country tone scheme
- Automatic fallback to PSTN and ISDN
- MWI light and missed calls notification can be configured

Enhancements:

- Support for new Gigaset handset's.(R630H PRO)

BugFixes:

- Various bugfixes

Known Issues:

- No busy tone with handsets SL910H, S820H, SL930H. Will be fixed in next SW release.
- DECT encryption signalling in menu: When switching off the encryption for old repeater (not 2.0 Repeater!), the checkmark will remain active in the box. But encryption is switched off. Just start registration!

Download URL:

How to update:

Via the webpage:

1. Settings » Management » Firmware update
2. Enter the URL for the new firmware in the **Data server** field: <http://profile.gigaset.net/device/latest>
3. Click on the button: **Update firmware**

| | | |
|------------------------|---------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Network | Firmware Update | |
| Telephony | Data server: | <input type="text" value="profile.gigaset.net/device"/> |
| Messaging | User defined firmware file: | <input type="text"/> |
| Info Services | Automatic check for software updates: | <input checked="" type="radio"/> Yes <input type="radio"/> No |
| Directories | | On starting the firmware update, the device checks if the requirements of a successful firmware download are fulfilled. The firmware is then downloaded without additional feedback. During the download and update, the handset / base connection is lost. A successful update results in the handset re-establishing the base connection. |
| Management | | <input type="button" value="Update firmware"/> |
| Date & Time | | |
| Local Settings | | |
| Miscellaneous | | |
| Reboot & Reset | | |
| Save & Restore | | |
| Firmware Update | | |

