

# Hybrid 120 Firmware 9.1 Revision 8 patch 2

## Release Date:

September 2014

## Version:

9.1 Revision 8 patch 2

## What is new?

- ...

## Enhancements.

- ...

## Bugfixes

- Calls could stuck at Call Transfer using SIP Trunk to SwyxWare
- Configuration of netmask at CIDR for Drop-in group was not possible
- irrelevant error messages on GUI at configuration of Drop-in group
- LDAP directory was empty after update of N510 to BL199
- occasionally wrong port numbers were set for NAT entries
- no incoming SIP calls possible using Toplink
- Failure in automatic route selection in combination with call through

## Known Issues

- ...



Download