

N510 IP PRO Release notes 42.250

Release date:

- June 2019

Improvements:

- After update to 248 TLS V1.1 not default
- [XSI phonebook] Only number in search (NAME)
- Handling excessive reINVITEs with RTP sent in the wrong codec
- Re-INVITE without SDP (MoH)
- Broadsoft (XSI) - Phonebook: Not possible to dial a number from "group" directory
- Broadsoft Conference (N-way)
- [Defining the time span when the device checks for updates](#)

BugFixes:

- ...

How to update:

Via the webpage:

1. Download the software and store this on your own accessible http server.
2. In the web-interface of the N510: Go to: **Settings » Management » Firmware update**
3. Enter the URL for the new firmware in the **User defined firmware file:** <http://profile.gigaset.net/device/latest>
4. Click on the button: **Update firmware**



Download