

# DX800 Release notes 158

## Release date:

02-2014

## Version:

158

## What's new:

- [Support of handsets with touch based user interface \(SL910H, S820H, SL930H\)](#)
- Support of Repeater 2.0
- [Country specific call progress tones](#)
- Supply dial tone on FXS port, depending on setting (FAX or phone use) and selected country tone scheme
- [Automatic fallback to PSTN and ISDN](#)
- MWI light and missed calls notification can be configured

## Enhancements:

- Support for new Gigaset handset's.(R630H PRO)

## BugFixes:

- Various bugfixes

## Known Issues:

- No busy tone with handsets SL910H, S820H, SL930H. Will be fixed in next SW release.
- DECT encryption signalling in menu: When switching off the encryption for old repeater (not 2.0 Repeater!), the checkmark will remain active in the box. But encryption is switched off. Just start registration!

## Download URL:

---

## How to update:

### Via the webpage:

1. Settings » Management » Firmware update
2. Enter the URL for the new firmware in the **Data server** field: <http://profile.gigaset.net/device/latest>
3. Click on the button: **Update firmware**

<b>Network</b>	<b>Firmware Update</b>
Telephony	Data server: <input type="text" value="profile.gigaset.net/device"/>
Messaging	User defined firmware file: <input type="text"/>
Info Services	Automatic check for software updates: <input checked="" type="radio"/> Yes <input type="radio"/> No
Directories	<p>On starting the firmware update, the device checks if the requirements of a successful firmware download are fulfilled. The firmware is then downloaded without additional feedback. During the download and update, the handset / base connection is lost. A successful update results in the handset re-establishing the base connection.</p> <input type="button" value="Update firmware"/>
Management	
Date & Time	
Local Settings	
Miscellaneous	
Reboot & Reset	
Save & Restore	
<b>Firmware Update</b>	

