

DX800 Release notes 173

Release date:

February 2015

Version:

173

What's new:

New since version 158:

- Support of Gigaset Repeater 2.0
- Support of the following PRO handsets: S650H PRO and SL750H PRO
- Country specific call progress tones are supported

Enhancements:

- ---

BugFixes:

- New/changed MSN-numbers were lost after power down (appeared only in versions 172 and 160)
- Phone calls may be initiated or accepted accidentally without user action
- Increased battery performance for touch based handsets registered
- Busy tone is audible on handsets when the caller terminates the call
- Various bug fixes

Known Issues:

- ---

Download URL:

How to update:

Via the webpage:

1. Settings » Management » Firmware update
2. Enter the URL for the new firmware in the **Data server** field: <http://profile.gigaset.net/device>
3. Click on the button: **Update firmware**

Network	Firmware Update
Telephony	Data server: <input type="text" value="profile.gigaset.net/device"/>
Messaging	User defined firmware file: <input type="text"/>
Info Services	Automatic check for software updates: <input checked="" type="radio"/> Yes <input type="radio"/> No
Directories	<p>On starting the firmware update, the device checks if the requirements of a successful firmware download are fulfilled. The firmware is then downloaded without additional feedback. During the download and update, the handset / base connection is lost. A successful update results in the handset re-establishing the base connection.</p> <input type="button" value="Update firmware"/>
Management	
Date & Time	
Local Settings	
Miscellaneous	
Reboot & Reset	
Save & Restore	
Firmware Update	

