

T640 T440 Release notes 1.0.1

Release date:

7 May 2015

Version:

1.0.1



Important

After installing this software the Media Gateway will automatically initiate a 3x time reboot (5-10 min). During this time any devices connected to the internal switch cannot be used and no changes to the system should be made.

What's new:

- [Changed CLIR behaviour to improve compatibility behind SIP trunk providers](#)

Enhancements:

- Change CED transfer mode and Fax signaling method for better T.38 compatibility
- Upgrade Media Gateway firmware.
 - Ethernet port status in port monitor
 - Increase transmission speed for incoming faxes on an analogue fax machines behind FXS port
- Added further translations for ES, IT, FR and NL

BugFixes:

- Maxwell 10 provisioning
- High load announcement in queues was not working and has been fixed
- Leading zeroes in passwords were ignored

Known Issues:

- ...



Unknown Attachment