

N510 IP PRO Release notes 42.081

Release date:

08-2013

Version:

42.081

What's new:

- Access code special treatment in call-list for Nordic customer.

Enhancements:

- DTMF control already at 180 ringing state and not only after 200 ok.
- Gigaset R630 support.
- Auto-provisioning update timer no reboot needed to activate.
- TR-069 - Zero Touch Activation
- Assign NTP server via DHCP
- Possibility to accept non trusted certificates automatically

BugFixes:

- Instability of Base-station in some environments.
- Language problem (Czech language)
- Radio-buttons for Date & Time are on wrong position
- SIP call cannot be answered when is made 2s after the last one
- New Parameters do not take effect after provisioning using plain XML content
- Changing the timer interval from 24h-random to a fix time stops the regular check
- Text on Info Services settings page is missing

Known Issues:

-

Download URL:

How to update:

Via the webpage:

1. Settings » Management » Firmware update
2. Enter the URL for the new firmware in the **User defined firmware file:** field
3. Click on the button: **Update firmware**

Network	Firmware Update	
Telephony	Data server:	<input type="text" value="profile.gigaset.net/device"/>
Messaging	User defined firmware file:	<input type="text"/>
Info Services	Automatic check for software updates:	<input checked="" type="radio"/> Yes <input type="radio"/> No
Directories	On starting the firmware update, the device checks if the requirements of a successful firmware download are fulfilled. The firmware is then downloaded without additional feedback. During the download and update, the handset / base connection is lost. A successful update results in the handset re-establishing the base connection.	
Management	<input type="button" value="Update firmware"/>	
Date & Time		
Local Settings		
Miscellaneous		
Reboot & Reset		
Save & Restore		
Firmware Update		

