

# DX800 Release notes 173

## Release date:

February 2015

## Version:

173

## What's new:

New since version 158:

- Support of Gigaset Repeater 2.0
- Support of the following PRO handsets: S650H PRO and SL750H PRO
- Country specific call progress tones are supported

## Enhancements:

- ---

## BugFixes:

- New/changed MSN-numbers were lost after power down (appeared only in versions 172 and 160)
- Phone calls may be initiated or accepted accidentally without user action
- Increased battery performance for touch based handsets registered
- Busy tone is audible on handsets when the caller terminates the call
- Various bug fixes

## Known Issues:

- ---

## Download URL:

## How to update:

### Via the webpage:

1. Settings » Management » Firmware update
2. Enter the URL for the new firmware in the **Data server** field: <http://profile.gigaset.net/device>
3. Click on the button: **Update firmware**

Network	<b>Firmware Update</b>
Telephony	Data server: <input type="text" value="profile.gigaset.net/device"/>
Messaging	User defined firmware file: <input type="text"/>
Info Services	Automatic check for software updates: <input checked="" type="radio"/> Yes <input type="radio"/> No
Directories	
Management	On starting the firmware update, the device checks if the requirements of a successful firmware download are fulfilled. The firmware is then downloaded without additional feedback. During the download and update, the handset / base connection is lost. A successful update results in the handset re-establishing the base connection.
Date & Time	<input type="button" value="Update firmware"/>
Local Settings	
Miscellaneous	
Reboot & Reset	
Save & Restore	
<b>Firmware Update</b>	

