N510 IP PRO Release notes 42.078

Release date:

06-2013

Version:

42.078

What's new:

Access code special treatment in call-list for Nordic customer

The feature is by default disabled (not available in the WEBUI) It can be enabled via provisioning. Values which has to be adapted:

Config Byte:

BS_CUSTOM.ucAkzVoipNotUsedNumberLength.

Values:

- 0x00 feature available in WebUI but not working
- 0x01-0x09 feature available in WebUI and working for numbers n-digits long and shorter
- 0xFF feature disabled (not available in webUI) the default one

Other values are not allowed

Enhancements:

• ...

BugFixes:

• Instability of Base-station in some environments.

Known Issues:

•

Download URL:

How to update:

Via the webpage:

- 1. Settings » Management » Firmware update
- 2. Enter the URL for the new firmware in the User defined firmware file: field
- 3. Click on the button: Update firmware



