

# FAQ Nx70 - Debugging Tool via cli access

## Introduction

If needed, you can start a pcap trace on the N870/N670 direct from your PC.

The trace can be made on the:


- DECT Manager + Base + Integrator
- DECT Base

Valid for:	
N670	N870

## Enable SSH access

First you need to enable SSH access to the system.

Open the web-interface and go to: **SETTINGS - System - Web configurator**.



The screenshot shows the Gigaset web interface. The left sidebar contains a menu with the following items: Network, Base stations, Provider or PBX profiles, Mobile devices, Telephony, Online directories, System (selected), Web configurator, Provisioning and configuration, Security, and System log. The main content area is titled 'Change password' and 'CLI access via ssh'. Under 'Change password', there are fields for 'New password (Admin)', 'Repeat password', and a 'Show password' checkbox. Under 'CLI access via ssh', there is a checkbox for 'Activated if password is longer than 7 characters' which is checked, and fields for 'CLI Password (Admin)' and 'Repeat password', both masked with dots, and a 'Show password' checkbox.

Enter the Password for the SSH access.

## Tools

[debug\\_n870\\_tracer.zip](#)

Unzip the file and just follow the instruction on the screen after starting the debug\_version.exe

You just have to enter the number of devices you like to trace, the IP address from your PC and IP addresses from all the devices you like to trace.