N510 IP PRO Release notes 42.263

Release date:

November 2022

Improvements:

• ...

BugFixes:

- Handshake fails because no suitable cipher suite is offered
- DTMF not work if 103 telephone-event/48000 is send in "INVITE"
- ptime for RTP is configured to 30ms but devices use 20 ms
- Reboot with groupcall 3 or more HS using UDP

How to update:

Via the webpage:

- 1. Download the software and store this on your own accessible http server.
- 2. In the web-interface of the N510: Go to: Settings » Management » Firmware update
- 3. Enter the URL for the new firmware in the **User defined firmware file:** http://profile.gigaset.net /device
- 4. Click on the button: Update firmware



Download