

T640 T440 Release notes 1.0.9

Release date:

February 2016

Version:

1.0.9



Important

The Media-gateway will be updated with new firmware (Improved fax support). This means when the update is started, the Media-gateway will reboot 3 times after the update is ready. The update of the Media Gateway takes ca. **15 minutes**.

!!! A system reboot is necessary when the IP-phones can't register to the PBX system **!!!**

New Gigaset DE900/700/410/310 **02.01.00** software is delivered with this software. To avoid upgrade errors during the reboot of the Media-gateway, the automatic device firmware update will be disabled.

You have to enable this after system is up and running via the menu **system Settings - Provisioning**

What's new:

- [Automatic/Manual Call Recording](#).
- Gigaset CTI Client is now supported. (The Gigaset CTI client is a paid solution, release in Q1/2016)

Enhancements:

- New Gigaset DE900/700/410/310 02.01.00 software is delivered with this upgrade. (DE-phone update has to be enabled manually after update via the menu **system Settings - Provisioning**)
- Play notification tone before manual recording of calls.
- Call waiting enabled by default when adding a new user.
- New feature [formatting of display name](#) has no influence anymore on incoming phone number. Incoming call will be displayed always with full name.
- Add support for Turkish language
- Sound level recordings improved.
- Set BRI DL ALWAYS UP Q.931 flag for VN6 lines
- Loading of phone book contacts/ call lists/ CDRs takes too long. Added multiple pages for contacts and call-lists.
- Extension monitor should have additional sorting criteria.
- Media gateway syslog server must be in the ip-address range 169.254.0.0/16.
- Fromuser and fromdomain are now shown in the sip.conf preview.
- Possibility to search in Contacts also using company name

BugFixes:

- Extension with same number as hunt group did not ring.
- Inbound missed calls are not registered correctly at the Voicemail list.
- Media-gateway new firmware to improve FAX transmission. MGW firmware version 6.60A.304.001
- Recording announcement, wrong language.
- Web-interface translation update.
- PHP warnings removed.
- Special characters break SIP password in preview of peer in sip.conf.
- In a Hunt Group: Forwarding to another group or to a voice mail box.

Known Issues:

- The AstButtonDaemon service stops after ca.30 minutes. This will affect the Extension/Queue Monitor, Display push-messages and partly the BLF functionality. A workaround is available [here](#).
- Hunt Group: Call forward on no answer is not working.

? Unknown Attachment