

Device Firmware update module

Introduction.

This module will enable you to put the latest device software on the Gigaset T300/T500. The devices can download the software from the PBX automatically.

The module can upload the software:

- Manual by selecting the file (No internet available)
- Automatically from Gigaset server
- Automatically from your own http server
- Online check for new firmware will be done automatically every .. time.



Important

If automatic update procedure PBX is enabled, devices will be updated automatically without your knowledge. **Advice is to disable this option** when the module is used and enable when Firmware updates are required/requested.

Manual Firmware update at e:

Configuration

Module Configuration: Update firmware

General Firmware update

Description

Download the special Firmware update file from the [Gigaset WIKI](#) site. This module will place the new Firmware files on the PBX.

Manual Firmware update

Info

After uploading the software, you need to disable and enable this module to update the firmware

Download software automatic ☒

Time to check update

Timer-Interval: Repeat every Day
Start (dd:mm:yyyy): Time (hh:mm):

URL to download server:

Firmware File Name:

Save

Apply

Cancel

Close

Will not work if Downloaded as a soft ware automatic is enabled. Select the Firmware file downloaded from this page.

Dis
a
bl
e
/
E
n
a
bl
e
m
o
d
ul
e
to
st
ar
t
u
p
d
at
e
pr
o
c
e
d
ur
e
i
m
m
e
di
at
e.

**A
u
t
o
m
at
ic
p
r
o
c
e
d
u
r
e:**

Dependent on selected time, the module will download a set of software automatically.

File will only be downloaded if file on server is newer than local file.

Default server URL will point to Gigaset server and will contain latest of fiscal release as determined.

Server URL can be changed to own server url.

Firmware file name can be changed, but if changed, will not download from G

ig
a
s
et
s
er
v
er
a
n
y
m
or
e.
S
h
o
ul
d
o
nl
y
b
e
c
h
a
n
g
e
d
if
y
o
u
u
s
e
y
o
ur
o
w
n
s
er
v
er
/fi
le
s.



Download the module V.39



Firmware file (14/01/2014) containing:

DE410/310 02.00.07
DE900/700 02.00.10
N510 SW version 194
N720 SW version 78