

Maxwell 10 Broadsoft

Introduction

Maxwell 10 with configured broadsoft account

Maxwell 10 and Broadsoft

If it is not possible to establish Audio calls, disabling all Video codecs solves problems